



October 20, 2005

OCT 28 2005
LBG

Mr. Sean Groszkowski
Leggette Brashear & Graham
110 Corporate Park Drive Suite 112
White Plains, NY 10604

Dear Mr. Groszkowski:

I am writing to inform you of revised analytical reports that are being issued for the following:

Project No. Charlton Cleaners

LLI Sample No.	Client Sample Identification	Collection Date
4600661	1st Floor - Loading Dock Grab Air Sample	09/09/2005
4600663	Basement - Equipment Room Grab Air Sample	09/09/2005

The correction to the data affects the EPA Method TO-15 analysis only.

During the final review of the data package, it was determined that additional dilutions should have been included in the analysis reports.

The value for tetrachloroethene in Lancaster Laboratories' (LLI) Sample No. 4600661 was reported as 380 $\mu\text{g}/\text{m}^3$. The value should have been reported from a 10 times dilution at a value of 320 $\mu\text{g}/\text{m}^3$.

The value for cis-1,2-dichloroethene in LLI Sample No. 4600663 was reported as 230 $\mu\text{g}/\text{m}^3$. The value should have been reported from a 10 times dilution at a value of 190 $\mu\text{g}/\text{m}^3$. The value for tetrachloroethene in LLI Sample No. 4600663 was reported as 2200 $\mu\text{g}/\text{m}^3$. The value should have been reported from a 40 times dilution at a value of 2600 $\mu\text{g}/\text{m}^3$. The revised analytical report reflects this correction and is enclosed.

You are a valued client and we apologize for any inconvenience that this incident may have caused. If you have any questions or require further assistance, please call me at 717-656-2300, Ext. 1864. We appreciate your business and look forward to continuing to serve your laboratory needs.

Sincerely,

George M. Main
Principal Chemist Group Leader
Volatiles in Air

GMM/mcs
Enclosures

cc: Richard Entz
Charles Neslund



REVISED

ANALYTICAL RESULTS

Prepared for:

Leggette Brashears & Graham
110 Corporate Park Drive
Suite 112
White Plains NY 10604

914-694-5177

Prepared by:

Lancaster Laboratories
2425 New Holland Pike
Lancaster, PA 17605-2425

SAMPLE GROUP

The sample group for this submittal is 958797. Samples arrived at the laboratory on Monday, September 12, 2005. The PO# for this group is CHARLTON CLEANERS.

Client Description

1st Floor - Store Area Grab Air Sample
1st Floor - Loading Dock Grab Air Sample
Basement - Main Area Grab Air Sample
Basement - Equipment Room Grab Air Sample

Lancaster Labs Number

4600660
4600661
4600662
4600663

METHODOLOGY

The specific methodologies used in obtaining the enclosed analytical results are indicated on the laboratory chronicles.

1 COPY TO
1 COPY TO

Leggette Brashears & Graham
Data Package Group

Attn: Sean Groszkowski



Lancaster Laboratories, Inc.
2425 New Holland Pike
PO Box 12425
Lancaster, PA 17605-2425
717-656-2300 Fax: 717-656-2681



Questions? Contact your Client Services Representative
Richard C Entz at (717) 656-2300

REVISED

Respectfully Submitted,

A handwritten signature in cursive script that reads "Rachel R. Cochis".

Rachel R. Cochis
Group Leader



Lancaster Laboratories Sample No. AQ 4600660

1st Floor - Store Area Grab Air Sample

Summa Canister # 0052

Charlton Cleaners

Collected: 09/09/2005 09:05 by SG

through 09/09/2005 17:10

Submitted: 09/12/2005 09:05

Reported: 10/20/2005 at 09:01

Discard: 11/20/2005

Account Number: 11827

Leggette Brashears & Graham

110 Corporate Park Drive

Suite 112

White Plains NY 10604

1STST SDG#: CHA01-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
05298	TO 15 VOA Ext. List					
07202	Dichlorodifluoromethane	75-71-8	5.0	1.0	ug/m3	1
07204	Freon 114	76-14-2	N.D.	1.0	ug/m3	1
07205	Chloromethane	74-87-3	3.0	0.40	ug/m3	1
07206	Vinyl Chloride	75-01-4	N.D.	0.50	ug/m3	1
07208	Bromomethane	74-83-9	N.D.	0.80	ug/m3	1
07209	Chloroethane	75-00-3	N.D.	0.50	ug/m3	1
07212	Trichlorofluoromethane	75-69-4	2.0 J	1.0	ug/m3	1
07215	1,1-Dichloroethene	75-35-4	N.D.	0.80	ug/m3	1
07216	Freon 113	76-13-1	N.D.	4.0	ug/m3	1
07221	3-Chloropropene	107-05-1	N.D.	2.0	ug/m3	1
07222	Methylene Chloride	75-09-2	3.0	2.0	ug/m3	1
07227	1,1-Dichloroethane	75-34-3	N.D.	0.80	ug/m3	1
07230	cis-1,2-Dichloroethene	156-59-2	7.0	0.80	ug/m3	1
07234	Chloroform	67-66-3	N.D.	1.0	ug/m3	1
07235	1,1,1-Trichloroethane	71-55-6	N.D.	1.0	ug/m3	1
07236	Carbon Tetrachloride	56-23-5	N.D.	1.0	ug/m3	1
07237	1,2-Dichloroethane	107-06-2	8.0	0.80	ug/m3	1
07238	Benzene	71-43-2	3.0	0.60	ug/m3	1
07241	Trichloroethene	79-01-6	2.0 J	1.0	ug/m3	1
07243	1,2-Dichloropropane	78-87-5	N.D.	0.90	ug/m3	1
07248	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.90	ug/m3	1
07250	Toluene	108-88-3	66.	0.80	ug/m3	1
07252	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.90	ug/m3	1
07254	1,1,2-Trichloroethane	79-00-5	N.D.	1.0	ug/m3	1
07255	Tetrachloroethene	127-18-4	90.	1.0	ug/m3	1
07258	1,2-Dibromoethane	106-93-4	N.D.	2.0	ug/m3	1
07259	Chlorobenzene	108-90-7	N.D.	0.90	ug/m3	1
07261	Ethylbenzene	100-41-4	12.	0.90	ug/m3	1
07262	m/p-Xylene	1330-20-7	28.	0.90	ug/m3	1
07263	o-Xylene	95-47-6	9.0	0.90	ug/m3	1
07264	Styrene	100-42-5	7.0	0.90	ug/m3	1
07267	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	1.0	ug/m3	1
07270	4-Ethyltoluene	622-96-8	5.0	1.0	ug/m3	1
07271	1,3,5-Trimethylbenzene	108-67-8	2.0 J	1.0	ug/m3	1
07273	1,2,4-Trimethylbenzene	95-63-6	8.0	1.0	ug/m3	1





Lancaster Laboratories Sample No. AQ 4600660

1st Floor - Store Area Grab Air Sample

Summa Canister # 0052

Charlton Cleaners

Collected: 09/09/2005 09:05 by SG

Account Number: 11827

through 09/09/2005 17:10

Submitted: 09/12/2005 09:05

Leggette Brashears & Graham

Reported: 10/20/2005 at 09:01

110 Corporate Park Drive

Discard: 11/20/2005

Suite 112

White Plains NY 10604

1STST SDG#: CHA01-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Dilution Factor
				Method	Units	
				Detection Limit		
07274	1,3-Dichlorobenzene	541-73-1	N.D.	3.0	ug/m3	1
07275	1,4-Dichlorobenzene	106-46-7	N.D.	3.0	ug/m3	1
07277	1,2-Dichlorobenzene	95-50-1	N.D.	3.0	ug/m3	1
07279	1,2,4-Trichlorobenzene	120-82-1	N.D.	7.0	ug/m3	1

Laboratory Chronicle

CAT No.	Analysis Name	Method	Analysis		Analyst	Dilution Factor
			Trial#	Date and Time		
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 03:51	Jeffrey B Smith	1





Lancaster Laboratories Sample No. AQ 4600661

1st Floor - Loading Dock Grab Air Sample

Summa Canister # 0043

Charlton Cleaners

Collected: 09/09/2005 09:08 by SG

through 09/09/2005 17:15

Submitted: 09/12/2005 09:05

Reported: 10/20/2005 at 09:01

Discard: 11/20/2005

Account Number: 11827

Leggette Brashears & Graham

110 Corporate Park Drive

Suite 112

White Plains NY 10604

1STLO SDG#: CHA01-02

CAT No.	Analysis Name	CAS Number	As Received		As Received		Dilution Factor
			Result		Method Detection Limit	Units	
05298	TO 15 VOA Ext. List						
07202	Dichlorodifluoromethane	75-71-8	3.0	J	1.0	ug/m3	1
07204	Freon 114	76-14-2	4.0	J	1.0	ug/m3	1
07205	Chloromethane	74-87-3	1.0	J	0.40	ug/m3	1
07206	Vinyl Chloride	75-01-4	2.0	J	0.50	ug/m3	1
07208	Bromomethane	74-83-9	N.D.		0.80	ug/m3	1
07209	Chloroethane	75-00-3	N.D.		0.50	ug/m3	1
07212	Trichlorofluoromethane	75-69-4	1.0	J	1.0	ug/m3	1
07215	1,1-Dichloroethene	75-35-4	N.D.		0.80	ug/m3	1
07216	Freon 113	76-13-1	N.D.		4.0	ug/m3	1
07221	3-Chloropropene	107-05-1	N.D.		2.0	ug/m3	1
07222	Methylene Chloride	75-09-2	N.D.		2.0	ug/m3	1
07227	1,1-Dichloroethane	75-34-3	N.D.		0.80	ug/m3	1
07230	cis-1,2-Dichloroethene	156-59-2	22.		0.80	ug/m3	1
07234	Chloroform	67-66-3	N.D.		1.0	ug/m3	1
07235	1,1,1-Trichloroethane	71-55-6	N.D.		1.0	ug/m3	1
07236	Carbon Tetrachloride	56-23-5	N.D.		1.0	ug/m3	1
07237	1,2-Dichloroethane	107-06-2	6.0		0.80	ug/m3	1
07238	Benzene	71-43-2	1.0	J	0.60	ug/m3	1
07241	Trichloroethene	79-01-6	4.0	J	1.0	ug/m3	1
07243	1,2-Dichloropropane	78-87-5	N.D.		0.90	ug/m3	1
07248	cis-1,3-Dichloropropene	10061-01-5	N.D.		0.90	ug/m3	1
07250	Toluene	108-88-3	49.		0.80	ug/m3	1
07252	trans-1,3-Dichloropropene	10061-02-6	N.D.		0.90	ug/m3	1
07254	1,1,2-Trichloroethane	79-00-5	N.D.		1.0	ug/m3	1
07255	Tetrachloroethene	127-18-4	320.		10.	ug/m3	10
07258	1,2-Dibromoethane	106-93-4	N.D.		2.0	ug/m3	1
07259	Chlorobenzene	108-90-7	N.D.		0.90	ug/m3	1
07261	Ethylbenzene	100-41-4	8.0		0.90	ug/m3	1
07262	m/p-Xylene	1330-20-7	18.		0.90	ug/m3	1
07263	o-Xylene	95-47-6	6.0		0.90	ug/m3	1
07264	Styrene	100-42-5	6.0		0.90	ug/m3	1
07267	1,1,2,2-Tetrachloroethane	79-34-5	N.D.		1.0	ug/m3	1
07270	4-Ethyltoluene	622-96-8	4.0	J	1.0	ug/m3	1
07271	1,3,5-Trimethylbenzene	108-67-8	2.0	J	1.0	ug/m3	1
07273	1,2,4-Trimethylbenzene	95-63-6	8.0		1.0	ug/m3	1





Lancaster Laboratories Sample No. AQ 4600661

1st Floor - Loading Dock Grab Air Sample

Summa Canister # 0043

Charlton Cleaners

Collected: 09/09/2005 09:08 by SG

Account Number: 11827

through 09/09/2005 17:15

Submitted: 09/12/2005 09:05

Leggette Brashears & Graham

Reported: 10/20/2005 at 09:01

110 Corporate Park Drive

Discard: 11/20/2005

Suite 112

White Plains NY 10604

1STLO SDG#: CHA01-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Dilution Factor
				Method Detection Limit	Units	
07274	1,3-Dichlorobenzene	541-73-1	N.D.	3.0	ug/m3	1
07275	1,4-Dichlorobenzene	106-46-7	N.D.	3.0	ug/m3	1
07277	1,2-Dichlorobenzene	95-50-1	N.D.	3.0	ug/m3	1
07279	1,2,4-Trichlorobenzene	120-82-1	N.D.	7.0	ug/m3	1

Laboratory Chronicle

CAT No.	Analysis Name	Method	Analysis		Analyst	Dilution Factor
			Trial#	Date and Time		
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 04:28	Jeffrey B Smith	10
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 05:06	Jeffrey B Smith	1





Lancaster Laboratories Sample No. AQ 4600662

Basement - Main Area Grab Air Sample
Summa Canister # 0342
Charlton Cleaners

Collected: 09/09/2005 09:11 by SG
through 09/09/2005 17:35
Submitted: 09/12/2005 09:05
Reported: 10/20/2005 at 09:01
Discard: 11/20/2005

Account Number: 11827

Leggette Brashears & Graham
110 Corporate Park Drive
Suite 112
White Plains NY 10604

BASMA SDG#: CHA01-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
05298	TO 15 VOA Ext. List					
07202	Dichlorodifluoromethane	75-71-8	3.0 J	1.0	ug/m3	1
07204	Freon 114	76-14-2	7.0	1.0	ug/m3	1
07205	Chloromethane	74-87-3	2.0	0.40	ug/m3	1
07206	Vinyl Chloride	75-01-4	2.0 J	0.50	ug/m3	1
07208	Bromomethane	74-83-9	N.D.	0.80	ug/m3	1
07209	Chloroethane	75-00-3	N.D.	0.50	ug/m3	1
07212	Trichlorofluoromethane	75-69-4	1.0 J	1.0	ug/m3	1
07215	1,1-Dichloroethene	75-35-4	N.D.	0.80	ug/m3	1
07216	Freon 113	76-13-1	N.D.	4.0	ug/m3	1
07221	3-Chloropropene	107-05-1	N.D.	2.0	ug/m3	1
07222	Methylene Chloride	75-09-2	2.0 J	2.0	ug/m3	1
07227	1,1-Dichloroethane	75-34-3	N.D.	0.80	ug/m3	1
07230	cis-1,2-Dichloroethene	156-59-2	120.	0.80	ug/m3	1
07234	Chloroform	67-66-3	N.D.	1.0	ug/m3	1
07235	1,1,1-Trichloroethane	71-55-6	N.D.	1.0	ug/m3	1
07236	Carbon Tetrachloride	56-23-5	N.D.	1.0	ug/m3	1
07237	1,2-Dichloroethane	107-06-2	21.	0.80	ug/m3	1
07238	Benzene	71-43-2	3.0	0.60	ug/m3	1
07241	Trichloroethene	79-01-6	20.	1.0	ug/m3	1
07243	1,2-Dichloropropane	78-87-5	N.D.	0.90	ug/m3	1
07248	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.90	ug/m3	1
07250	Toluene	108-88-3	92.	0.80	ug/m3	1
07252	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.90	ug/m3	1
07254	1,1,2-Trichloroethane	79-00-5	N.D.	1.0	ug/m3	1
07255	Tetrachloroethene	127-18-4	1,200.	14.	ug/m3	10
07258	1,2-Dibromoethane	106-93-4	N.D.	2.0	ug/m3	1
07259	Chlorobenzene	108-90-7	N.D.	0.90	ug/m3	1
07261	Ethylbenzene	100-41-4	14.	0.90	ug/m3	1
07262	m/p-Xylene	1330-20-7	30.	0.90	ug/m3	1
07263	o-Xylene	95-47-6	11.	0.90	ug/m3	1
07264	Styrene	100-42-5	16.	0.90	ug/m3	1
07267	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	1.0	ug/m3	1
07270	4-Ethyltoluene	622-96-8	5.0	1.0	ug/m3	1
07271	1,3,5-Trimethylbenzene	108-67-8	3.0 J	1.0	ug/m3	1
07273	1,2,4-Trimethylbenzene	95-63-6	11.	1.0	ug/m3	1





Lancaster Laboratories Sample No. AQ 4600662

Basement - Main Area Grab Air Sample
Summa Canister # 0342
Charlton Cleaners

Collected: 09/09/2005 09:11 by SG
through 09/09/2005 17:35
Submitted: 09/12/2005 09:05
Reported: 10/20/2005 at 09:01
Discard: 11/20/2005

Account Number: 11827

Leggette Brashears & Graham
110 Corporate Park Drive
Suite 112
White Plains NY 10604

BASMA SDG#: CHA01-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Dilution Factor
				Method Detection Limit	Units	
07274	1,3-Dichlorobenzene	541-73-1	N.D.	3.0	ug/m3	1
07275	1,4-Dichlorobenzene	106-46-7	N.D.	3.0	ug/m3	1
07277	1,2-Dichlorobenzene	95-50-1	N.D.	3.0	ug/m3	1
07279	1,2,4-Trichlorobenzene	120-82-1	N.D.	7.0	ug/m3	1

Laboratory Chronicle

CAT No.	Analysis Name	Method	Analysis		Analyst	Dilution Factor
			Trial#	Date and Time		
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 05:44	Jeffrey B Smith	10
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 06:21	Jeffrey B Smith	1





Lancaster Laboratories Sample No. AQ 4600663

Basement - Equipment Room Grab Air Sample

Summa Canister # 0144

Charlton Cleaners

Collected: 09/09/2005 09:15 by SG

through 09/09/2005 17:40

Submitted: 09/12/2005 09:05

Reported: 10/20/2005 at 09:01

Discard: 11/20/2005

Account Number: 11827

Leggette Brashears & Graham

110 Corporate Park Drive

Suite 112

White Plains NY 10604

BASEQ SDG#: CHA01-04

CAT No.	Analysis Name	CAS Number	As Received Result		As Received	Units	Dilution Factor
					Method Detection Limit		
05298	TO 15 VOA Ext. List						
07202	Dichlorodifluoromethane	75-71-8	3.0	J	1.0	ug/m3	1
07204	Freon 114	76-14-2	4.0	J	1.0	ug/m3	1
07205	Chloromethane	74-87-3	1.0	J	0.40	ug/m3	1
07206	Vinyl Chloride	75-01-4	17.		0.50	ug/m3	1
07208	Bromomethane	74-83-9	N.D.		0.80	ug/m3	1
07209	Chloroethane	75-00-3	N.D.		0.50	ug/m3	1
07212	Trichlorofluoromethane	75-69-4	1.0	J	1.0	ug/m3	1
07215	1,1-Dichloroethene	75-35-4	N.D.		0.80	ug/m3	1
07216	Freon 113	76-13-1	N.D.		4.0	ug/m3	1
07221	3-Chloropropene	107-05-1	N.D.		2.0	ug/m3	1
07222	Methylene Chloride	75-09-2	N.D.		2.0	ug/m3	1
07227	1,1-Dichloroethane	75-34-3	N.D.		0.80	ug/m3	1
07230	cis-1,2-Dichloroethene	156-59-2	190.		8.0	ug/m3	10
07234	Chloroform	67-66-3	N.D.		1.0	ug/m3	1
07235	1,1,1-Trichloroethane	71-55-6	N.D.		1.0	ug/m3	1
07236	Carbon Tetrachloride	56-23-5	N.D.		1.0	ug/m3	1
07237	1,2-Dichloroethane	107-06-2	13.		0.80	ug/m3	1
07238	Benzene	71-43-2	2.0	J	0.60	ug/m3	1
07241	Trichloroethene	79-01-6	34.		1.0	ug/m3	1
07243	1,2-Dichloropropane	78-87-5	N.D.		0.90	ug/m3	1
07248	cis-1,3-Dichloropropene	10061-01-5	N.D.		0.90	ug/m3	1
07250	Toluene	108-88-3	33.		0.80	ug/m3	1
07252	trans-1,3-Dichloropropene	10061-02-6	N.D.		0.90	ug/m3	1
07254	1,1,2-Trichloroethane	79-00-5	N.D.		1.0	ug/m3	1
07255	Tetrachloroethene	127-18-4	2,600.		56.	ug/m3	40
07258	1,2-Dibromoethane	106-93-4	N.D.		2.0	ug/m3	1
07259	Chlorobenzene	108-90-7	N.D.		0.90	ug/m3	1
07261	Ethylbenzene	100-41-4	8.0		0.90	ug/m3	1
07262	m/p-Xylene	1330-20-7	16.		0.90	ug/m3	1
07263	o-Xylene	95-47-6	6.0		0.90	ug/m3	1
07264	Styrene	100-42-5	8.0		0.90	ug/m3	1
07267	1,1,2,2-Tetrachloroethane	79-34-5	N.D.		1.0	ug/m3	1
07270	4-Ethyltoluene	622-96-8	3.0	J	1.0	ug/m3	1
07271	1,3,5-Trimethylbenzene	108-67-8	1.0	J	1.0	ug/m3	1
07273	1,2,4-Trimethylbenzene	95-63-6	5.0		1.0	ug/m3	1





Lancaster Laboratories Sample No. AQ 4600663

Basement - Equipment Room Grab Air Sample

Summa Canister # 0144

Charlton Cleaners

Collected: 09/09/2005 09:15 by SG

Account Number: 11827

through 09/09/2005 17:40

Submitted: 09/12/2005 09:05

Leggette Brashears & Graham

Reported: 10/20/2005 at 09:01

110 Corporate Park Drive

Discard: 11/20/2005

Suite 112

White Plains NY 10604

BASEQ SDG#: CHA01-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Dilution Factor
				Method Detection Limit	Units	
07274	1,3-Dichlorobenzene	541-73-1	N.D.	3.0	ug/m3	1
07275	1,4-Dichlorobenzene	106-46-7	N.D.	3.0	ug/m3	1
07277	1,2-Dichlorobenzene	95-50-1	N.D.	3.0	ug/m3	1
07279	1,2,4-Trichlorobenzene	120-82-1	N.D.	7.0	ug/m3	1

Laboratory Chronicle

CAT No.	Analysis Name	Method	Analysis		Analyst	Dilution Factor
			Trial#	Date and Time		
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 06:59	Jeffrey B Smith	10
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 07:37	Jeffrey B Smith	1
05298	TO 15 VOA Ext. List	EPA Method TO-15	1	09/26/2005 19:44	Jeffrey B Smith	40



Quality Control Summary

Client Name: Leggette Brashears & Graham
Reported: 10/20/05 at 09:01 AM

Group Number: 958797

Matrix QC may not be reported if site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

Laboratory Compliance Quality Control

Analysis Name	Blank Result	Blank MDL	Report Units	LCS %REC	LCSD %REC	LCS/LCSD Limits	RPD	RPD Max
Batch number: C052683ZA	Sample number(s): 4600660-4600663							
Dichlorodifluoromethane	N.D.	0.20	ppb (v)	106		70-130		
Freon 114	N.D.	0.20	ppb (v)	106		70-130		
Chloromethane	N.D.	0.20	ppb (v)	93		70-130		
Vinyl Chloride	N.D.	0.20	ppb (v)	96		47-141		
Bromomethane	N.D.	0.20	ppb (v)	101		70-130		
Chloroethane	N.D.	0.20	ppb (v)	100		70-130		
Trichlorofluoromethane	N.D.	0.20	ppb (v)	110		70-130		
1,1-Dichloroethene	N.D.	0.20	ppb (v)	99		70-130		
Freon 113	N.D.	0.50	ppb (v)	109		70-130		
3-Chloropropene	N.D.	0.20	ppb (v)					
Methylene Chloride	N.D.	0.50	ppb (v)	101		70-130		
1,1-Dichloroethane	N.D.	0.20	ppb (v)	94		70-130		
cis-1,2-Dichloroethene	N.D.	0.20	ppb (v)	92		70-130		
Chloroform	N.D.	0.20	ppb (v)	104		70-130		
1,1,1-Trichloroethane	N.D.	0.20	ppb (v)	107		61-150		
Carbon Tetrachloride	N.D.	0.20	ppb (v)	100		70-130		
1,2-Dichloroethane	N.D.	0.20	ppb (v)	108		70-130		
Benzene	N.D.	0.20	ppb (v)	100		56-146		
Trichloroethene	N.D.	0.20	ppb (v)	102		54-147		
1,2-Dichloropropane	N.D.	0.20	ppb (v)	101		70-130		
cis-1,3-Dichloropropene	N.D.	0.20	ppb (v)	86		70-130		
Toluene	N.D.	0.20	ppb (v)	95		70-130		
trans-1,3-Dichloropropene	N.D.	0.20	ppb (v)	93		70-130		
1,1,2-Trichloroethane	N.D.	0.20	ppb (v)	88		70-130		
Tetrachloroethene	N.D.	0.20	ppb (v)	97		70-130		
1,2-Dibromoethane	N.D.	0.20	ppb (v)	98		70-130		
Chlorobenzene	N.D.	0.20	ppb (v)	95		70-130		
Ethylbenzene	N.D.	0.20	ppb (v)	96		65-127		
m/p-Xylene	N.D.	0.20	ppb (v)	96		70-130		
o-Xylene	N.D.	0.20	ppb (v)	103		70-130		
Styrene	N.D.	0.20	ppb (v)	100		70-130		
1,1,2,2-Tetrachloroethane	N.D.	0.20	ppb (v)	93		70-130		
4-Ethyltoluene	N.D.	0.20	ppb (v)					
1,3,5-Trimethylbenzene	N.D.	0.20	ppb (v)	97		70-130		
1,2,4-Trimethylbenzene	N.D.	0.20	ppb (v)	94		70-130		
1,3-Dichlorobenzene	N.D.	0.50	ppb (v)	103		70-130		

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.





Quality Control Summary

Client Name: Leggette Brashears & Graham

Group Number: 958797

Reported: 10/20/05 at 09:01 AM

Laboratory Compliance Quality Control

<u>Analysis Name</u>	<u>Blank</u> <u>Result</u>	<u>Blank</u> <u>MDL</u>	<u>Report</u> <u>Units</u>	<u>LCS</u> <u>%REC</u>	<u>LCSD</u> <u>%REC</u>	<u>LCS/LCSD</u> <u>Limits</u>	<u>RPD</u>	<u>RPD Max</u>
1,4-Dichlorobenzene	N.D.	0.50	ppb (v)	100		29-134		
1,2-Dichlorobenzene	N.D.	0.50	ppb (v)	100		70-130		
1,2,4-Trichlorobenzene	N.D.	1.0	ppb (v)	94		70-130		

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.



Lancaster Laboratories, Inc.
2425 New Holland Pike
PO Box 12425
Lancaster, PA 17605-2425
717-656-2300 Fax: 717-656-2681