

APPENDIX E

**MONITORING REPORTS ON CD,
SITE PHOTOS, PHOTOLOG ON CD**

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and Staff	Construction/Demolition Equipment
Envirotrac-Remedial Contractor	JS and Staff	Drilling Equipment & Excavator
FPM Group	BC, JKB, AM	PID, noise monitor and dust monitor

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Air and noise monitoring. Installation of sub slab soil vapor implants.
Ball Construction	Renovation of Site building.
Envirotrac	Well and remedial system piping installation.

Weather Conditions
Weather conditions during the month of November have been generally warmer then typical. Occasional storms with gusting winds and precipitation were noted.

Monitoring				
	Dust (ug/m ³)		Noise (db)	Organic Vapors (ppm)
	Low	High	Average	
Background	5	50	80	0
Work Zone	20	120	90	0
Downwind	5	85	80	0
Comments	All monitoring was conducted in accordance with the approved HASP and CAMP. No exceedances of the HASP or CAMP were noted.			

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment Envirotrac – Procurement and installation of remedial system equipment.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and Staff	Construction/Demolition Equipment
Envirotrac-Remedial Contractor	JS and Staff	Excavator
FPM Group	BC, JKB, AM	PID, noise monitor and dust monitor

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Air and noise monitoring; soil removal oversight.
Ball Construction	Renovation of Site building.
Envirotrac	Remedial system piping repair.

Weather Conditions					
	AM/PM (12/04/06)	AM/PM (12/05/06)	AM/PM (12/06/06)	AM/PM (12/07/06)	AM/PM (12/08/06)
Temperature, estimated (°F)	-	-	35/40	40/50	30/35
Weather Conditions	-	-	Sunny	Sunny/Partly Cloudy	Partly Cloudy
Prevailing Wind, estimated (mph)	-	-	10/15	Calm/10	10/15
Wind Gusts?	-	-	No	No	No/20
Wind Direction	-	-	South	NA/South	North

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	12/04/06	12/05/06	12/06/06	12/07/06	12/08/06	12/04/06	12/05/06	12/06/06	12/07/06	12/08/06
Background	-	-	112	110	96	-	-	74	85	91
Work Zone	-	-	91	82	118	-	-	85	88	90
Downwind	-	-	99	90	113	-	-	85	88	90
Organic Vapors (ppm)	-	-	0	0	0	-	-	0	0	0
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Procurement and installation of remedial system equipment.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and Staff	Construction/Demolition Equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	AM, JKB	PID, noise monitor and dust monitor

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Air and noise monitoring; soil removal oversight.
Ball Construction	Renovation of Site building.
Envirotrac	N/A

Weather Conditions					
	AM/PM (12/11/06)	AM/PM (12/12/06)	AM/PM (12/13/06)	AM/PM (12/14/06)	AM/PM (12/15/06)
Temperature, estimated (°F)	45/55	45/50	50	45/55	40/50
Weather Conditions	Partly Cloudy/Sunny	Cloudy	Overcast, light rain	Hazy	Hazy
Prevailing Wind, estimated (mph)	Calm/5 mph	5/10	Calm	Calm/5	5/5
Wind Gusts?	No	No	5-10 mph	No	No
Wind Direction	NA/South	South	South	NA/South	South

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	12/11/06	12/12/06	12/13/06	12/14/06	12/15/06	12/11/06	12/12/06	12/13/06	12/14/06	12/15/06
Background	100	74	10	283	168	60	75	-	60	72
Work Zone	86	84	100	254	216	73	76	-	73	65
Downwind	83	94	60	258	218	71	74	-	73	68
Organic Vapors (ppm)	0	0	0	0	0	0	0	0	0	0
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring; soil removal oversight. Ball Construction- Continued site redevelopment; soil removal. Envirotrac – None.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and Staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	Staff	Piping installation equipment
FPM Group	JKB, MS	PID, noise monitor and dust monitor

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Air and noise monitoring..
Ball Construction	Renovation of Site building.
Envirotrac	Installation of remediation piping.

Weather Conditions					
	AM/PM (12/18/06)	AM/PM (12/19/06)	AM/PM (12/20/06)	AM (12/21/06)	AM (12/22/06)
Temperature, estimated (°F)	NA	NA	50	45	40
Weather Conditions	NA	NA	Light Rain	Cloudy	Overcast
Prevailing Wind, estimated (mph)	NA	NA	Calm	0-5	5-10
Wind Gusts?	NA	NA	5-10	10	No
Wind Direction	NA	NA	East/Southeast	Northwest	East

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	12/18/06	12/19/06	12/20/06	12/21/06	12/22/06	12/18/06	12/19/06	12/20/06	12/21/06	12/22/06
Background	NA	NA	10	80	20	NA	NA	NA	NA	NA
Work Zone	NA	NA	100	100	80	NA	NA	NA	NA	NA
Downwind	NA	NA	50	100	50	NA	NA	NA	NA	NA
Organic Vapors (ppm)	NA	NA	0	0	0	NA	NA	NA	NA	NA
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Installation of remediation piping.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	None	N/A
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	None.
Envirotrac	None.

Weather Conditions					
	AM/PM (12/25/06)	AM/PM (12/26/06)	AM/PM (12/27/06)	AM (12/28/06)	AM (12/29/06)
Temperature, estimated (°F)	NA	NA	NA	NA	NA
Weather Conditions	NA	NA	NA	NA	NA
Prevailing Wind, estimated (mph)	NA	NA	NA	NA	NA
Wind Gusts?	NA	NA	NA	NA	NA
Wind Direction	NA	NA	NA	NA	NA

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	12/15/06	12/26/06	12/27/06	12/28/06	12/29/06	12/25/06	12/26/06	12/27/06	12/28/06	12/29/06
Background	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Work Zone	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Downwind	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Organic Vapors (ppm)	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Comments	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	JS and staff	Piping installation equipment
FPM Group	BC, JKB	PID, noise monitoring and dust monitor

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Oversee installation of remediation system piping.
Ball Construction	Site redevelopment.
Envirotrac	Install remediation system piping.

Weather Conditions					
	AM/PM (1/1/07)	AM/PM (1/2/07)	AM/PM (1/3/07)	AM (1/4/07)	AM (1/5/07)
Temperature, estimated (°F)	N/A	42	36/52	42	50
Weather Conditions		Sunny	Partly Cloudy	Partly Sunny	Cloudy
Prevailing Wind, estimated (mph)		10 to 15	Calm	Calm	Calm
Wind Gusts?		No	No	No	10
Wind Direction		Southwest	NA	Various	Various

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	1/1/07	1/2/07	1/3/07	1/4/07	1/5/07	1/1/07	1/2/07	1/3/07	1/4/07	1/5/07
Background	N/A	30	50	50	30	N/A				
Work Zone		57	73	90	N/A					
Downwind		57	73	75	N/A					
Organic Vapors (ppm)		0	0	0	0					
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	JS and staff	Piping installation equipment
FPM Group	BC, JB	PID, noise monitoring and dust monitor

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Oversee installation of remediation system piping; air and noise monitoring.
Ball Construction	Site redevelopment.
Envirotrac	Install remediation system piping.

Weather Conditions					
	AM/PM (1/8/07)	AM/PM (1/9/07)	AM/PM (1/10/07)	AM (1/11/07)	AM (1/12/07)
Temperature, estimated (°F)	N/A	35	30/35	30	N/A
Weather Conditions		Sunny	Sunny	Sunny	
Prevailing Wind, estimated (mph)		N/A	5	N/A	
Wind Gusts?		N/A	Occasional	N/A	
Wind Direction		N/A	Northeast	N/A	

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	1/8/07	1/9/07	1/10/07	1/11/07	1/12/07	1/8/07	1/9/07	1/10/07	1/11/07	1/12/07
Background	N/A	30	50	30	N/A	N/A	72	74	70	N/A
Work Zone		50	70	40			76	75	75	
Downwind		40	70	40			74	75	70	
Organic Vapors (ppm)		0	0	0			0	0	0	
Comments		-	-	-			-	-	-	

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (1/15/07)	AM/PM (1/16/07)	AM/PM (1/17/07)	AM (1/18/07)	AM (1/19/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	1/15/07	1/16/07	1/17/07	1/18/07	1/19/07	1/15/07	1/16/07	1/17/07	1/18/07	1/19/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (1/22/07)	AM/PM (1/23/07)	AM/PM (1/24/07)	AM (1/25/07)	AM (1/26/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	1/22/07	1/23/07	1/24/07	1/25/07	1/26/07	1/22/07	1/23/07	1/24/07	1/25/07	1/26/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (1/29/07)	AM/PM (1/30/07)	AM/PM (1/31/07)	AM (2/1/07)	AM (2/2/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	1/29/07	1/30/07	1/31/07	2/1/07	2/2/07	1/29/07	1/30/07	1/31/07	2/1/07	2/2/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (2/5/07)	AM/PM (2/6/07)	AM/PM (2/7/07)	AM/PM (2/8/07)	AM/PF (2/9/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	2/5/07	2/6/07	2/7/07	2/8/07	2/9/07	2/5/07	2/6/07	2/7/07	2/8/07	2/9/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (2/12/07)	AM/PM (2/13/07)	AM/PM (2/14/07)	AM/PM (2/15/07)	AM/PM (2/16/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	2/12/07	2/13/07	2/14/07	2/15/07	2/16/07	2/12/07	2/13/07	2/14/07	2/15/07	2/16/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (2/19/07)	AM/PM (2/20/07)	AM/PM (2/21/07)	AM/PM (2/22/07)	AM/PM (2/23/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	2/19/07	2/20/07	2/21/07	2/22/07	2/23/07	2/19/07	2/20/07	2/21/07	2/22/07	2/23/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (2/26/07)	AM/PM (2/27/07)	AM/PM (2/28/07)	AM/PM (3/1/07)	AM/PM (3/2/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	2/26/07	2/27/07	2/28/07	3/1/07	3/2/07	2/26/07	2/27/07	2/28/07	3/1/07	3/2/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction equipment
Envirotrac-Remedial Contractor	None	N/A
FPM Group	None	N/A

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM/PM (3/5/07)	AM/PM (3/6/07)	AM/PM (3/7/07)	AM/PM (3/8/07)	AM/PM (3/9/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	3/5/07	3/6/07	3/7/07	3/8/07	3/9/07	3/5/07	3/6/07	3/7/07	3/8/07	3/9/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	None	-
FPM Group	JB	Air monitoring during construction.

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Air monitoring during construction.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM (3/12/07)	AM/PM (3/13/07)	AM/PM (3/14/07)	AM (3/15/07)	AM (3/16/07)
Temperature, estimated (°F)	30	N/A			
Weather Conditions	Partly Cloudy				
Prevailing Wind, estimated (mph)	10				
Wind Gusts?	No				
Wind Direction	West				

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	3/12/07	3/13/07	3/14/07	3/15/07	3/16/07	3/12/07	3/13/07	3/14/07	3/15/07	3/16/07
Background	N/A	N/A				N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)	0									
Comments	-									

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	None	-
FPM Group	None	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	None.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM (3/19/07)	AM/PM (3/20/07)	AM/PM (3/21/07)	AM (3/22/07)	AM (3/23/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	3/19/07	3/20/07	3/21/07	3/22/07	3/23/07	3/19/07	3/20/07	3/21/07	3/22/07	3/23/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments										

Community Contacts
Community Contacts: N/A
FPM Response: N/A

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	None	-
FPM Group	JB, JKB	PID

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Soil removal oversight; stockpile screening.
Ball Construction	Site redevelopment.
Envirotrac	None.

Weather Conditions					
	AM (3/26/07)	AM/PM (3/27/07)	AM/PM (3/28/07)	AM (3/29/07)	AM (3/30/07)
Temperature, estimated (°F)	NA			40	41
Weather Conditions				Clear	Partly Cloudy
Prevailing Wind, estimated (mph)				10	10
Wind Gusts?				20	None
Wind Direction				Variable	West

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	3/26/07	3/27/07	3/28/07	3/29/07	3/30/07	3/26/07	3/27/07	3/28/07	3/29/07	3/30/07
Background	NA			NA		NA				
Work Zone										
Downwind										
Organic Vapors (ppm)				0	0	-	-	-	-	-
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	JW	Pressure testing equipment
FPM Group	SOD	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Observation of piping pressure tests.
Ball Construction	Site redevelopment.
Envirotrac	Piping pressure tests.

Weather Conditions					
	AM/PM (4/2/07)	AM/PM (4/3/07)	AM/PM (4/4/07)	AM/PM (4/5/07)	AM/PM (4/6/07)
Temperature, estimated (°F)	N/A	N/A	N/A	35	N/A
Weather Conditions				Sunny, windy	
Prevailing Wind, estimated (mph)				20	
Wind Gusts?				Yes	
Wind Direction				North	

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	4/2/07	4/3/07	4/4/07	4/5/07	4/6/07	4/2/07	4/3/07	4/4/07	4/5/07	4/6/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	JW	Pressure testing equipment
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	Piping pressure tests.

Weather Conditions					
	AM/PM (4/9/07)	AM/PM (4/10/07)	AM/PM (4/11/07)	AM/PM (4/12/07)	AM/PM (4/13/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	4/9/07	4/10/07	4/11/07	4/12/07	4/13/07	4/9/07	4/10/07	4/11/07	4/12/07	4/13/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (4/16/07)	AM/PM (4/17/07)	AM/PM (4/18/07)	AM/PM (4/19/07)	AM/PM (4/20/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	4/16/07	4/17/07	4/18/07	4/19/07	4/20/07	4/16/07	4/17/07	4/18/07	4/19/07	4/20/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (4/23/07)	AM/PM (4/24/07)	AM/PM (4/25/07)	AM/PM (4/26/07)	AM/PM (4/27/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	4/23/07	4/24/07	4/25/07	4/26/07	4/27/07	4/23/07	4/24/07	4/25/07	4/26/07	4/27/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (4/30/07)	AM/PM (5/1/07)	AM/PM (5/2/07)	AM/PM (5/3/07)	AM/PM (5/4/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	4/30/07	5/1/07	5/2/07	5/3/07	5/4/07	4/30/07	5/1/07	5/2/07	5/3/07	5/4/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (5/7/07)	AM/PM (5/8/07)	AM/PM (5/9/07)	AM/PM (5/10/07)	AM/PM (5/11/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	5/7/07	5/8/07	5/9/07	5/10/07	5/11/07	5/7/07	5/8/07	5/9/07	5/10/07	5/11/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (5/14/07)	AM/PM (5/15/07)	AM/PM (5/16/07)	AM/PM (5/17/07)	AM/PM (5/18/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	5/14/07	5/15/07	5/16/07	5/17/07	5/18/07	5/14/07	5/15/07	5/16/07	5/17/07	5/18/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (5/21/07)	AM/PM (5/22/07)	AM/PM (5/23/07)	AM/PM (5/24/07)	AM/PM (5/25/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	5/21/07	5/22/07	5/23/07	5/24/07	5/25/07	5/21/07	5/22/07	5/23/07	5/24/07	5/25/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	Driller & assistant	Drill rig
FPM Group	JKB	PID

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Well installation oversight, air quality monitoring.
Ball Construction	Site redevelopment.
Envirotrac	Remedial well installation

Weather Conditions					
	AM/PM (5/28/07)	AM/PM (5/29/07)	AM/PM (5/30/07)	AM/PM (5/31/07)	AM/PM (6/1/07)
Temperature, estimated (°F)	N/A				75/88
Weather Conditions					Hazy sunshine, humid
Prevailing Wind, estimated (mph)					Light
Wind Gusts?					5 to 10
Wind Direction					Variable

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	5/28/07	5/29/07	5/30/07	5/31/07	6/1/07	5/28/07	5/29/07	5/30/07	5/31/07	6/1/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)	-	-	-	-	0	-	-	-	-	-
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction, well installation.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (6/4/07)	AM/PM (6/5/07)	AM/PM (6/6/07)	AM/PM (6/7/07)	AM/PM (6/8/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	6/4/07	6/5/07	6/6/07	6/7/07	6/8/07	6/4/07	6/5/07	6/6/07	6/7/07	6/8/07
Background										
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (6/11/07)	AM/PM (6/12/07)	AM/PM (6/13/07)	AM/PM (6/14/07)	AM/PM (6/15/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	6/11/07	6/12/07	6/13/07	6/14/07	6/15/07	6/11/07	6/12/07	6/13/07	6/14/07	6/15/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	AM	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Air monitoring.
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (6/18/07)	AM/PM (6/19/07)	AM/PM (6/20/07)	AM/PM (6/21/07)	AM/PM (6/22/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	6/18/07	6/19/07	6/20/07	6/21/07	6/22/07	6/18/07	6/19/07	6/20/07	6/21/07	6/22/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)	N/A	N/A	N/A	0	N/A					
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (6/25/07)	AM/PM (6/26/07)	AM/PM (6/27/07)	AM/PM (6/28/07)	AM/PM (6/29/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	6/25/07	6/26/07	6/27/07	6/28/07	6/29/07	6/25/07	6/26/07	6/27/07	6/28/07	6/29/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Performed sub-slab and indoor air sampling.
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (7/2/07)	AM/PM (7/3/07)	AM/PM (7/4/07)	AM/PM (7/5/07)	AM/PM (7/6/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	7/2/07	7/3/07	7/4/07	7/5/07	7/6/07	7/2/07	7/3/07	7/4/07	7/5/07	7/6/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (7/9/07)	AM/PM (7/10/07)	AM/PM (7/11/07)	AM/PM (7/12/07)	AM/PM (7/13/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	7/9/07	7/10/07	7/11/07	7/12/07	7/13/07	7/9/07	7/10/07	7/11/07	7/12/07	7/13/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (7/16/07)	AM/PM (7/17/07)	AM/PM (7/18/07)	AM/PM (7/19/07)	AM/PM (7/20/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	7/16/07	7/17/07	7/18/07	7/19/07	7/20/07	7/16/07	7/17/07	7/18/07	7/19/07	7/20/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	BTC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Groundwater monitoring
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (7/23/07)	AM/PM (7/24/07)	AM/PM (7/25/07)	AM/PM (7/26/07)	AM/PM (7/27/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	7/23/07	7/24/07	7/25/07	7/26/07	7/27/07	7/23/07	7/24/07	7/25/07	7/26/07	7/27/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	BTC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (7/30/07)	AM/PM (7/31/07)	AM/PM (8/1/07)	AM/PM (8/2/07)	AM/PM (8/3/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	7/30/07	7/31/07	8/1/07	8/2/07	8/3/07	7/30/07	7/31/07	8/1/07	8/2/07	8/3/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (8/6/07)	AM/PM (8/7/07)	AM/PM (8/8/07)	AM/PM (8/9/07)	AM/PM (8/10/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	8/6/07	8/7/07	8/8/07	8/9/07	8/10/07	8/6/07	8/7/07	8/8/07	8/9/07	8/10/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Ball Construction – General Contractor	JG and staff	Construction/demolition equipment
Envirotrac-Remedial Contractor	-	-
FPM Group	-	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	N/A
Ball Construction	Site redevelopment.
Envirotrac	N/A

Weather Conditions					
	AM/PM (8/13/07)	AM/PM (8/14/07)	AM/PM (8/15/07)	AM/PM (8/16/07)	AM/PM (8/17/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	8/13/07	8/14/07	8/15/07	8/16/07	8/17/07	8/13/07	8/14/07	8/15/07	8/16/07	8/17/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed. Ball Construction- Continued site redevelopment. Envirotrac – Remediation system construction.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	Staff	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system startup on 8/23/07
Envirotrac	Remediation system startup on 8/23/07

Weather Conditions					
	AM/PM (8/20/07)	AM/PM (8/21/07)	AM/PM (8/22/07)	AM/PM (8/23/07)	AM/PM (8/24/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	8/20/07	8/21/07	8/22/07	8/23/07	8/24/07	8/20/07	8/21/07	8/22/07	8/23/07	8/24/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	Staff	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring on 8/28/07.
Envirotrac	Remediation system adjustments on 8/30/07.

Weather Conditions					
	AM/PM (8/27/07)	AM/PM (8/28/07)	AM/PM (8/29/07)	AM/PM (8/30/07)	AM/PM (8/31/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	8/27/07	8/28/07	8/29/07	8/30/07	8/31/07	8/27/07	8/28/07	8/29/07	8/30/07	8/31/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	NA	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring.
Envirotrac	NA

Weather Conditions					
	AM/PM (9/3/07)	AM/PM (9/4/07)	AM/PM (9/5/07)	AM/PM (9/6/07)	AM/PM (9/7/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	9/3/07	9/4/07	9/5/07	9/6/07	9/7/07	9/3/07	9/4/07	9/5/07	9/6/07	9/7/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	NA	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring.
Envirotrac	NA

Weather Conditions					
	AM/PM (9/10/07)	AM/PM (9/11/07)	AM/PM (9/12/07)	AM/PM (9/13/07)	AM/PM (9/14/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	9/10/07	9/11/07	9/12/07	9/13/07	9/14/07	9/10/07	9/11/07	9/12/07	9/13/07	9/14/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	NA	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring.
Envirotrac	NA

Weather Conditions					
	AM/PM (9/17/07)	AM/PM (9/18/07)	AM/PM (9/19/07)	AM/PM (9/20/07)	AM/PM (9/21/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	9/17/07	9/18/07	9/19/07	9/20/07	9/21/07	9/17/07	9/18/07	9/19/07	9/20/07	9/21/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	NA	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring.
Envirotrac	NA

Weather Conditions					
	AM/PM (9/24/07)	AM/PM (9/25/07)	AM/PM (9/26/07)	AM/PM (9/27/07)	AM/PM (9/28/07)
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
	9/24/07	9/25/07	9/26/07	9/27/07	9/28/07	9/24/07	9/25/07	9/26/07	9/27/07	9/28/07
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	NA	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring on October 4 and October 8, 2007
Envirotrac	NA

Weather Conditions					
	AM/PM	AM/PM	AM/PM	AM/PM	AM/PM
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	NA	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring on November 6 & 20, 2007
Envirotrac	NA

Weather Conditions					
	AM/PM	AM/PM	AM/PM	AM/PM	AM/PM
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.

PROGRESS REPORT

Location: 90-30 Metropolitan Avenue, Rego Park, NY

Site # V00253-2

Organizations	Staff	Equipment
Envirotrac-Remedial Contractor	NA	-
FPM Group	BC	-

On-Site Visitors	Purpose
N/A	N/A

Description of Daily Activities	
FPM	Remediation system monitoring on December 12 and December 27, 2007
Envirotrac	NA

Weather Conditions					
	AM/PM	AM/PM	AM/PM	AM/PM	AM/PM
Temperature, estimated (°F)	N/A				
Weather Conditions					
Prevailing Wind, estimated (mph)					
Wind Gusts?					
Wind Direction					

Monitoring										
	Dust (ug/m ³)					Noise (DBA)				
Background	N/A					N/A				
Work Zone										
Downwind										
Organic Vapors (ppm)										
Comments	-	-	-	-	-	-	-	-	-	-

Community Contacts
Community Contacts: NA
FPM Response: NA

Planned Activities
<ul style="list-style-type: none"> FPM – Air and noise monitoring, as needed; remediation system monitoring.




Photo #1 – View of south side of building prior to redevelopment and remedial system installation.



Photo #2 – View of remedial system well installation.



Photo #3 – View of remedial piping installation.



Photo #4 – View of remedial system compound.



Photo #5 – View of remedial system components.



Photo #7 – View of remedial system components.



Photo #6 – View of remedial system components.



Photo #8 – View of remedial system components.



Photo #9 – View of remedial system components.



Photo #10 – South side of building following remedial system installation.



Photo #11 – View of remedial system compound and stack.