

New York Department of Environmental Conservation  
Division of Environmental Remediation  
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#1

**Date:** October 3, 2005 Monday  
**Site Name:** Greif Bros. Facility  
**Site Number:** V00334-9  
**Location:** 2122 Colvin Blvd.  
Tonawanda(T), Erie County  
**Project Manager:** M.. Hinton Region 9  
**Consulting Engineer:** ERM (for Greif Bros.)  
**Contractor:** Pinto Construction Co.  
**Job Phone:** 870-1407 (DEC cell)

**Weather Conditions:** hazy sun, 75°

**Description of Work Performed:**

set up equipment trailer and laborer shed, mobilized track backhoe to the site.

**Items of Concern/Comments:**

ERM e-mail indicated that intrusive activities may begin 10/4. First job meeting scheduled for 10/12. DEC unable to attend.

**HEALTH & SAFETY:**

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: n/a

**SITE VISITORS:** none

**CONTRACTORS INFORMATION:** Pinto Construction Co.

**Subcontractors:** Darling Construction Co.

Prime Contractors Hours Worked: n/a

Subcontractors: n/a

**EQUIPMENT:**

JD 450 LC track hoe

**WORK FORCE:**

**Pinto Construction Co.:**

**Darling Construction Co.:**

**Inspector's Name:** Jim Tuk \_\_\_\_\_ Sanitary Const. Insp. II

**Date:** 10/19/05

**field:** 1345-1355

**Distribution:** G. Sutton \_\_\_\_\_/file

M. Hinton \_\_\_\_\_ Via e-mail

**Attachments:** none

