

New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#2

Date: October 4, 2005 Tuesday
Site Name: Greif Bros. Facility
Site Number: V00334-9
Location: 2122 Colvin Blvd.
Tonawanda(T), Erie County
Project Manager: M.. Hinton Region 9
Consulting Engineer: ERM (for Greif Bros.)
Contractor: Pinto Construction Co.
Job Phone: 870-1407 (DEC cell)

Weather Conditions: sunny, 73°

Description of Work Performed:
setting up exclusion zone fencing.

Items of Concern/Comments:
Contractor will begin excavating week of 10/10.

HEALTH & SAFETY:
PPE: D
Is the PPE in conformance with the specifications? : y
Are atmospheric monitoring results at acceptable levels?: n/a

SITE VISITORS: none

CONTRACTORS INFORMATION: Pinto Construction Co.
Subcontractors: Darling Construction Co.
Prime Contractors Hours Worked: 0700-1530
Subcontractors: n/a

EQUIPMENT:
JD 450 LC track hoe

WORK FORCE:
ERM: J. Fox
Pinto Construction Co.: 1 laborer
Darling Construction Co.: n/a

Inspector's Name: Jim Tuk _____ Sanitary Const. Insp. II
Date: 10/19/05
field: 1115-1200

Distribution: G. Sutton _____/file
M. Hinton _____ Via e-mail

Attachments: none

