

New York Department of Environmental Conservation  
Division of Environmental Remediation  
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#3

**Date:** October 13, 2005 Thursday  
**Site Name:** Greif Bros. Facility  
**Site Number:** V00334-9  
**Location:** 2122 Colvin Blvd.  
Tonawanda(T), Erie County  
**Project Manager:** M.. Hinton Region 9  
**Consulting Engineer:** ERM (for Greif Bros.)  
**Contractor:** Pinto Construction Co.  
**Job Phone:** 870-1407 (DEC cell)

**Weather Conditions:** partly sunny, 66°, NW<10

**Description of Work Performed:**

exclusion zone fence, temporary soil staging areas, excavating top foot in work zone.

**Items of Concern/Comments:**

ERM checking each bucket of excavated soil with FID, staging as non haz.  
Darling scheduled to mobilize 10/18.

**HEALTH & SAFETY:**

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: y

**SITE VISITORS:** none

**CONTRACTORS INFORMATION:** Pinto Construction Co.

**Subcontractors:** Darling Construction Co.

Prime Contractors Hours Worked: 0700-1530

Subcontractors: n/a

**EQUIPMENT:**

JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks

**WORK FORCE:**

**ERM:** 1

**Pinto Construction Co.:** 2 laborers, 1 operator

**Darling Construction Co.:** n/a

**Inspector's Name:** Jim Tuk \_\_\_\_\_ Sanitary Const. Insp. II

**Date:** 10/19/05

**field:** 1245-1510

**Distribution:** G. Sutton \_\_\_\_\_ /file

M. Hinton \_\_\_\_\_ Via e-mail

**Attachments:** digital photos

