

New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#4

Date: October 17, 2005 Monday
Site Name: Greif Bros. Facility
Site Number: V00334-9
Location: 2122 Colvin Blvd.
Tonawanda(T), Erie County
Project Manager: M.. Hinton Region 9
Consulting Engineer: ERM (for Greif Bros.)
Contractor: Pinto Construction Co.
Job Phone: 870-1407 (DEC cell)

Weather Conditions: partly sunny, 52°, NW<10

Description of Work Performed:
removing piping from known concrete vault.

Items of Concern/Comments:
contractor located drain line to be relocated. Will do this on 10/18 and do vault demoltion.
HFD mobilized a crane to the site.
ERM may switch job meeting to 10/20, will notify DEC if so.

HEALTH & SAFETY:
PPE: D
Is the PPE in conformance with the specifications? : y
Are atmospheric monitoring results at acceptable levels?: y

SITE VISITORS: none

CONTRACTORS INFORMATION: Pinto Construction Co.
Subcontractors: Darling Construction Co.
Prime Contractors Hours Worked: 0700-1530
Subcontractors: n/a

EQUIPMENT:
JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks

WORK FORCE:
ERM: 2
Pinto Construction Co.: 1 laborer, 1 operator
Darling Construction Co.: n/a

Inspector's Name: Jim Tuk _____ Sanitary Const. Insp. II
Date: 10/19/05
field: 1140-1210

Distribution: G. Sutton _____ /file
M. Hinton _____ Via e-mail

Attachments: digital photos