

New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#8

Date: October 26, 2005 Wednesday
Site Name: Greif Bros. Facility
Site Number: V00334-9
Location: 2122 Colvin Blvd.
Tonawanda(T), Erie County
Project Manager: M.. Hinton Region 9
Consulting Engineer: ERM (for Greif Bros.)
Contractor: Pinto Construction Co.
Job Phone: 870-1407 (DEC cell)

Weather Conditions: overcast, 45°, N<10

Description of Work Performed:

Subcontractor is setting sheets prior to driving for remediation of the former drum storage area.

Items of Concern/Comments:

ERM has contracted with EWMI for waste disposal. They will grab samples from soil stockpile Thursday for waste characterization.

HEALTH & SAFETY:

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: y

SITE VISITORS: none

CONTRACTORS INFORMATION: Pinto Construction Co.

Subcontractors: Darling Construction Co.

Prime Contractors Hours Worked: 0730-1600

Subcontractors: 0730-1600

EQUIPMENT:

JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks, American crane

WORK FORCE:

ERM: 3

Pinto Construction Co.: 1

Darling Construction Co.: 3

Inspector's Name: Jim Tuk _____ Sanitary Const. Insp. II

Date: 10/28/05

field: 1515-1600

Distribution: G. Sutton _____/file

M. Hinton _____ Via e-mail

Attachments: none