

New York Department of Environmental Conservation  
Division of Environmental Remediation  
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#10

**Date:** November 1, 2005 Tuesday  
**Site Name:** Greif Bros. Facility  
**Site Number:** V00334-9  
**Location:** 2122 Colvin Blvd.  
Tonawanda(T), Erie County  
**Project Manager:** M.. Hinton Region 9  
**Consulting Engineer:** ERM (for Greif Bros.)  
**Contractor:** Pinto Construction Co.  
**Job Phone:** 870-1407 (DEC cell)

**Weather Conditions:** rain, 57°, W10-15

**Description of Work Performed:**

Subcontractor continues driving sheet piling for remediation of the former drum storage area.

**Items of Concern/Comments:**

Sheet piling work should be completed today and HFD will demobilize Wednesday.

**HEALTH & SAFETY:**

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: n/a

**SITE VISITORS:** none

**CONTRACTORS INFORMATION:** Pinto Construction Co.

**Subcontractors:** Darling Construction Co.

Prime Contractors Hours Worked: 0730-1600

Subcontractors: 0730-1600

**EQUIPMENT:**

JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks, Amer. crane

**WORK FORCE:**

**ERM:** 2

**Pinto Construction Co.:** 1

**Darling Construction Co.:** 3

**Inspector's Name:** Jim Tuk \_\_\_\_\_ Sanitary Const. Insp. II

**Date:** 11/02/05

**field:** 1020-1045

**Distribution:** G. Sutton \_\_\_\_\_ /file

M. Hinton \_\_\_\_\_ Via e-mail

**Attachments:** none

