

New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#13

Date: November 7, 2005 Monday
Site Name: Greif Bros. Facility
Site Number: V00334-9
Location: 2122 Colvin Blvd.
Tonawanda(T), Erie County
Project Manager: M.. Hinton Region 9
Consulting Engineer: ERM (for Greif Bros.)
Contractor: Pinto Construction Co.
Job Phone: 870-1407 (DEC cell)

Weather Conditions: partly cloudy, 48°, W15-20

Description of Work Performed:

Contractor excavated interior of cell to 5' bgs, subcontractor preparing to install bracing.

Items of Concern/Comments:

Contractor is using foam suppressant to control odors.
Owner has signed waste profile, offsite disposal still planned for Thursday.

HEALTH & SAFETY:

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: Y

SITE VISITORS: M. Hinton

CONTRACTORS INFORMATION: Pinto Construction Co.

Subcontractors: Darling Construction Co.

Prime Contractors Hours Worked: 0730-1600

Subcontractors: 0730-1600

EQUIPMENT:

JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks, Amer. crane

WORK FORCE:

ERM: 2

Pinto Construction Co.: 1

Darling Construction Co.: 5

Inspector's Name: Jim Tuk _____ I _____ Sanitary Const. Insp. II

Date: 11/08/05

field: 1400-1600

Distribution: G. Sutton _____ /file
M. Hinton _____ Via e-mail

Attachments: digital photos

