

New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#17

Date: November 22, 2005 Tuesday
Site Name: Greif Bros. Facility
Site Number: V00334-9
Location: 2122 Colvin Blvd.
Tonawanda(T), Erie County
Project Manager: M.. Hinton Region 9
Consulting Engineer: ERM (for Greif Bros.)
Contractor: Pinto Construction Co.
Job Phone: 870-1407 (DEC cell)

Weather Conditions: mostly cloudy, 30°, N15-20

Description of Work Performed:

Contractor completed excavating haz soil in cell per Work Plan. Is backfilling cell with crusher run stone and compacting.

Items of Concern/Comments:

Two small stockpiles remain(haz and non haz soil) to be disposed offsite.

HEALTH & SAFETY:

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: Y

SITE VISITORS: none

CONTRACTORS INFORMATION: Pinto Construction Co.

Subcontractors: Darling Construction Co.

Prime Contractors Hours Worked: 0730-1600

Subcontractors:

EQUIPMENT:

JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks, Amer. crane

WORK FORCE:

ERM: 1

Pinto Construction Co.: 3

Darling Construction Co.: 0

Inspector's Name: Jim Tuk _____ I _____ Sanitary Const. Insp. II

Date: 11/22/05

field: 1305-1330

Distribution: G. Sutton _____ /file

M. Hinton _____ Via e-mail

Attachments: digital photos