

New York Department of Environmental Conservation  
Division of Environmental Remediation  
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#21

**Date:** December 15, 2005 Thursday  
**Site Name:** Greif Bros. Facility IRM  
**Site Number:** V00334-9  
**Location:** 2122 Colvin Blvd.  
Tonawanda(T), Erie County  
**Project Manager:** M.. Hinton Region 9  
**Consulting Engineer:** ERM (for Greif Bros.)  
**Contractor:** Pinto Construction Co.  
**Job Phone:** 870-1407 (DEC cell)

**Weather Conditions:** overcast, 23°, S<10

**Description of Work Performed:**

Contractor excavated GP10 to remove contaminated soil. Completed excavating soil on the south side of the sheet piling cell and disposed that soil off site.

**Items of Concern/Comments:**

Attended Progress Meeting #8, some notes:

- Pinto plans to demobilize from site next week.
- ~1750 tons of haz soil disposal estimated by ERM. GP10 soil to be removed from site on Tuesday. Pinto estimated 2000 tons of stone have been imported to site. ~700 gallons of water will be disposed offsite next week.
- Final inspection scheduled for 12/22. Greif Bros. to determine final surface cover.

Final progress meeting is 12/15.

**HEALTH & SAFETY:**

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: n/a

**SITE VISITORS:** M. Hinton

**CONTRACTORS INFORMATION:** Pinto Construction Co.

**Subcontractors:**

Prime Contractors Hours Worked: 0730-1600

**EQUIPMENT:**

JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks

**WORK FORCE:**

ERM: 3

Pinto Construction Co.: 4

**Inspector's Name:** Jim Tuk \_\_\_\_\_ Sanitary Const. Insp. II

**Date:** 12/15/05

**field:** 0955-1115

**Distribution:** G. Sutton \_\_\_\_\_/file  
M. Hinton \_\_\_\_\_ Via e-mail

**Attachments:** digital photos