

# INSPECTION REPORT

**Site Number:** V-00334-9/915525  
**Site Name:** Grief Bros. Corporation  
**Location:** 2122 Colvin Blvd, Tonawanda  
**Project Manager:** Michael J. Hinton  
**Project Engineer:** Jon Fox ERM  
**Job Phone:** N/A

**Date:** August 27, 2009

**HEALTH & SAFETY:** PPE: Level D  
Is the PPE level in conformance with the specifications: N/A  
Are atmospheric monitoring results at acceptable levels? N/A

## DESCRIPTION OF WORK PERFORMED:

MJH on site at 1125 hrs

Weather - partly cloudy, south west wind, T~70°F

ERM - Rob Sents, Todd \_\_\_\_\_

Marcor - 2 employees

Nothnagel - off site

Air monitoring in place - all normal

ERM monitoring wells at 0800 hrs- DNAPL collecting in sumps and wells:

VP-1 dry

VP-2 0.2' DNAPL removed ~0.5 gallons

VP-3 1.4' DNAPL removed ~3 gallons

Sump - Removed ~18 gallons since sump last pumped out at 1200 hrs 8/26/2009

ERM to continue to monitor wells and sump for the next couple fo days. System to removed collected DNAPL will be set up for the weekend.

MJH left site at 1155 hrs

## Attachments:

**Inspector's Name (Print):** Michael J. Hinton

**Inspector's Signature:**

**Date:** August 31, 2009