

# INSPECTION REPORT

**Site Number:** V-00334-9/915525  
**Site Name:** Grief Bros. Corporation  
**Location:** 2122 Colvin Blvd, Tonawanda  
**Project Manager:** Michael J. Hinton  
**Project Engineer:** Jon Fox ERM  
**Job Phone:** N/A

**Date:** August 31, 2009

**HEALTH & SAFETY:** PPE: Level D  
Is the PPE level in conformance with the specifications: N/A  
Are atmospheric monitoring results at acceptable levels? N/A

## DESCRIPTION OF WORK PERFORMED:

MJH on site at 1400 hrs

Weather - mostly sunny, south wind, T~70°F

Air handling equipment operating. No odors detected in work area.

Automatic DNAPL recovery pumps in place and operating in VP-2, VP-3 and sump. Appears to be very little recovered DNAPL in drums.

MJH left site at 1410 hrs

**Attachments:** Photo's


**Inspector's Name (Print):** Michael J. Hinton

**Inspector's Signature:**

**Date:** August 31, 2009



083109-01 VP-2 VP-3 .JPG



083109-02 VP-3.JPG