

INSPECTION REPORT

Site Number: V-00334-9/915525

Date: May 26, 2011

Site Name: Grief Bros. Corporation

Location: 2122 Colvin Blvd, Tonawanda

Project Manager: Michael J. Hinton

Project Engineer: Jon Fox ERM

Job Phone: N/A

HEALTH & SAFETY: PPE: Level D

Is the PPE level in conformance with the specifications: N/A

Are atmospheric monitoring results at acceptable levels? N/A

DESCRIPTION OF WORK PERFORMED:

MJH on site at 1010 hrs

Weather – T~60⁰F, mostly cloudy, East Wind, humid overnight and early morning heavy rains

ERM – Dave Myers

Pinto – operator, foreman and 3 laborers

Pinto backfilling excavation with washed 2' ROB gravel due to water in excavation from rain and application of chemical augmentation. Placing 1' of 2" ROB in bottom of hole then will place on-site soil for reuse over gravel and finish off hole with 0-2' ROB gravel.

System running

MJH left site at 1045 hrs.

Attachments: Photo's

Inspector's Name (Print): Michael J. Hinton

Inspector's Signature:


Date: May 26, 2011



2611-01 Washed #2 ROB Backfill.j



2611-02 Washed #2 ROB gravel.jj



2611-03 Washed #2 ROB gravel.jj



052611-04 Soil Storage Cell.jpg