



**Division of Environmental Remediation
Remedial Bureau C, Central Office**

Field Log

| | |
|----------------------------|-------------------------|
| Site Code #: V00415 | Date: 01/22/2026 |
|----------------------------|-------------------------|

Site Name: Orange Plaza Shopping Center
Location: 444-480 (NY-211) Dunning Farm Road East, Walkkill/Middleton, NY 12589
DEC Project Manager: Matthew Hubicki

| | AM | PM |
|-----------------------|-----------------------|-----------|
| Weather | Partly Cloudy | N/A |
| Temperature | 35 deg F | N/A |
| Wind Direction | South-Southwest 8 mph | N/A |

Objective: Inspection site cover, monitoring well, and surrounding parking lot and the Kohls store downgradient.

Description of Inspection Activities and Discussions:

Meet with Langan to go over the former dry cleaner, site management, and former remedial work. PRR due 4/06/26. Current space or parking lot was home to the demolished dry cleaner in 2001. This paved parking lot for the current Kohls Department Store.

Keith McPartland was present from Langan to check the site cover (parking lot) and prep the monitoring well for sampling on February 2nd.

Health & Safety:

Level of protection: Level D, with safety vests.

Site Representative: Matt Hubicki

Date: 3/24/2026

Representative's Signature:

GW-5 or MW-1 Looking North towards Red Lobster & NY 211 East



Looking South in Front Kohl's



Looking East towards Walmart Supercenter



Looking West towards Burlington Coat Store



