



SITE INSPECTION REPORT

Site Name: Buffalo Business Park

Site Number: V00663

Location: 1800 Broadway, Buffalo NY

Inspection Date: 1/13/2026

NYSDEC Project Manager: Bradley Demo

Weather Conditions: Cloudy, 34°F

Personnel Onsite: Natalie O. (C&S Companies)

Description of Work Performed: Well sampling

Details:

- Monitoring well OS-4 was sampled for Volatile Organic Compounds with QA/QC samples taken. Sample was taken after ≈ 1 hour for parameters to stabilize. No elevated PID readings, odors, or high turbidity was noted from the well. Depth to water prior to purging was 4.5 fbgs and depth to bottom was measured as 13.84 fbgs. OS-4 is a 2inch diameter, PVC well. Purge water was containerized and would be disposed of properly per C&S.
- Unidentified well next to OS-4 was unable to be accessed. Monitoring well OS-5 was also unable to be accessed due to stripped bolt heads on the well cover.

Inspector: Bradley Demo

Signature: *Bradley W. Demo*

Attachments: Photolog

Site Inspection Report

Buffalo Business Park (Site V00663)

January 13, 2026

Page 2

Photolog:



Measuring OS-4 depth. The twin well behind was unable to be accessed.