


Norlite, LLC



628 SO. SARATOGA STREET
PO BOX 684
COHOES, NY 12047
PHONE: (518) 235-0401
FAX: (518) 235-0233

June 13th, 2016

James Quinn
NYS Department of Environmental Conservation-Region 4
Division of Environmental Remediation
1130 North Westcott Road
Schenectady, NY 12306

Re: Request for Minor Permit Modification to Current Part 373 Permit
EPA ID# NYD080469935

Dear Mr. Quinn:

This letter and the attachment constitute a request for a minor modification to Norlite's current Part 373 Permit.

Norlite LLC (Norlite) has conducted a repair of TK-200C. The 'Post-Repair Integrity Assessment' report, prepared by Harvey King, P.E. is provided for the department's review. The submittal also includes a modified drawing No. 1 of 1-Replace 10 Feet of Shell & Lower Head on Tank 200C (NY003-92023-200C). This drawing will act as a replacement for TK-200C in the drawing previously referenced for TK-200C in No. NY003-92023-1 for TK-200B/C. The modified drawing incorporates foot note five (5) which details the maximum allowable specific gravity of 1.7 as per the mixer design. With NYSDEC approval, the drawing will be incorporated into the RCRA Part 373 permit in Attachment B. This is documented in the required permit modification log, also attached.

Norlite appreciates the Department's consideration of this request.

Should you have any questions regarding this letter, please contact me at (518) 235-0401 or email at: Prince.Knight@tradebe.com. Thank you.

Sincerely,

Prince M Knight III

Prince M. Knight III
Laboratory, Environmental & Compliance Manager

Enc. Interior LGF TANK POST-REPAIR ASSESSMENT REPORT For TANK 200C_2016 FINAL
ecc: Michael Cruden, NYS DEC
Thomas Killeen, NYSDEC
David Lates, NYS DEC
Joseph Hadersbeck, NYS DEC
Darrell Monk – Norlite
Eric Stager - Tradebe